



Note: After any field seam is completed, it must be probed to ensure that a secure weld has been made.

REVISED: 01/30/2017	GENERAL DETAIL
PREVIOUS: 01/01/2009	FIELD SEAMING
SCALE: NONE	NEW CONSTRUCTION OR RE-ROOF